



re: Slope Stability Assessment
Proposed Residential Development
122 Old Mill Lane – Appleton, Ontario

to: Southwell Homes Ltd. - **Mr. John Southwell** – johnsouthwell@rogers.com

date: November 10, 2023

file: PG6241-MEMO.01 Revision 1

Further to your request and authorization, Paterson Group (Paterson) prepared the current memorandum to provide the slope stability assessment for the proposed residential development to be located at the aforementioned site.

The following sections provide a summary of our analysis of the slope conditions and recommendations to achieve stable slope setbacks for the proposed development.

1.0 Proposed Development

Based on the review of the drawings provided by the client, it is understood that the proposed residential development will consist of single-family residential dwellings with associated driveways, roadways, and access lanes. It is further anticipated that the proposed development will be privately serviced, with a septic system at the rear of each dwelling.

2.0 Field Observations

Paterson conducted subsurface investigations in 2008, 2015, 2016 and 2018 which consisted of advancing a total of 56 test pits and 5 boreholes to a maximum depth of 12.1 m below the existing ground surface. The locations of the test holes are shown on Drawing PG6241-1 – Limit of Hazard Lands Plan attached to this report.

Further, Paterson conducted a site visit on April 20, 2022 to review the site conditions and complete an assessment of the slope located along the northern boundary of the subject site. Two (2) slope cross-sections (Sections A-A and B-B) were studied as the worst-case scenarios. The cross-section locations are presented on Drawing PG6241-1 – Limit of Hazard Lands Plan attached to this report. The following provides a summary of the field observations and assessment.





Surface Conditions

The subject site is located along the south shore of the Mississippi River and adjacent to the Appleton Swamp. The subject site is currently undeveloped.

At lots 1 through 4, the existing ground surface is generally level at approximate geodetic elevation 126 to 128 m, but slopes downward moderately in the vicinity of the Mississippi River to approximate geodetic elevation 118 m. At lots 5 through 11, the ground surface slopes downward gradually at the northern portions of the lots, from approximate geodetic elevation 127 to 122 m, before reaching an approximately 10 to 40 m wide plateau, and then sloping downward more moderately in the vicinity of the Mississippi River from about geodetic elevation 122 to 118 m. At Lots 12 through 14, the ground surface is generally level at approximate geodetic elevation 128 m.

Subsurface Profile

Generally, the soil profile at the subject site consists of a thin layer of topsoil or fill underlain by bedrock. A layer of variable thickness of silty sand or silty clay, and a discontinuous glacial till, were also encountered underlying the fill at various test holes. The fill layer extends down to depths ranging between approximately 0.2 to 7.0 m below ground surface, and was observed to consist of brown silty sand and/or sandy silt, some gravel, and variable amounts of crushed stone, concrete, organics, glass, metal, or plastic debris.

Practical refusal to excavation or augering was encountered in several test holes at approximate depths ranging between 0.1 and 3.0 m below ground surface.

Reference should be made to the Soil Profile and Test Data sheets, attached to this report, for the details of the subsurface soil profile encountered at each test hole location.

Bedrock

Based on the available geological mapping, the subject site is underlain by dolostone of the Oxford Formation.

Groundwater

Groundwater levels were measured during the previous subsurface investigations. The measured groundwater level readings are provided on the Soil Profile and Test Data sheets attached to the present report.

However, it should be noted that the groundwater levels can fluctuate periodically throughout the year and higher levels could be encountered at the time of construction.



3.0 Slope Stability Assessment

The slope conditions at the subject site were reviewed by Paterson field personnel on April 20, 2022. Photographs from our site visit are attached following this memo. Paterson also surveyed the top of slope location on this date using a mobile GPS unit.

The slopes at the subject site are generally well vegetated with no observed signs of active erosion. Three (3) slope cross-sections (Sections A-A, B-B, and C-C) were studied as the worst-case scenarios. The cross-section locations are presented on Drawing PG6241-1 – Limit of Hazard Lands Plan attached to the current memo report.

A slope stability analysis was carried out to evaluate the stability of the slope under existing and proposed conditions.

Slope Stability Assessment

The analyses of the stability of the slopes were carried out using SLIDE, a computer program which permits a two-dimensional slope stability analysis using several methods, including the Bishop's method, which is a widely used and accepted analysis method. The program calculates a factor of safety, which represents the ratio of the forces resisting failure to those favouring failure. Theoretically, a factor of safety of 1.0 represents a condition where the slope is stable.

However, due to intrinsic limitations of the calculation methods and the variability of the subsoil and groundwater conditions, a factor of safety greater than 1.0 is usually required to ascertain that the risks of failure are acceptable. Minimum factors of safety of 1.5 and 1.1 are generally recommended for static and seismic analysis conditions, respectively, where the failure of the slope would endanger permanent structures.

The cross-sections were analyzed based on the existing conditions observed during our site visit, and review of the available topographic mapping. The slope stability analysis was completed at each slope cross-section under worst-case-scenario by assigning cohesive soils under fully saturated conditions. Subsoil conditions at the cross-sections were inferred based on nearby boreholes and general knowledge of the area's geology.

The effective strength soil parameters used for static analysis were chosen based on the subsoil information recovered during the geotechnical investigation. The effective strength soil parameters used for static analysis are presented in Table 1 on the following page.



| Soil Layer | Unit Weight (kN/m ³) | Friction Angle (degrees) | Cohesion (kPa) |
|------------------|----------------------------------|--------------------------|----------------|
| Topsoil | 16 | 33 | 5 |
| Fill | 18 | 33 | 0 |
| Brown Silty Clay | 17 | 33 | 5 |
| Silty Sand | 20 | 35 | 0 |
| Glacial Till | 20 | 35 | 1 |
| Bedrock | 22 | - | 1,000 |

The total strength parameters for seismic analysis were chosen based on the subsurface conditions observed in the test holes, and our general knowledge of the geology in the area. The strength parameters used for seismic analysis at the slope cross-sections are presented in Table 2 below.

| Soil Layer | Unit Weight (kN/m ³) | Friction Angle (degrees) | Undrained Shear Strength (kPa) |
|------------------|----------------------------------|--------------------------|--------------------------------|
| Topsoil | 16 | 33 | 5 |
| Fill | 18 | 33 | 0 |
| Brown Silty Clay | 17 | - | 100 |
| Silty Sand | 20 | 35 | 0 |
| Glacial Till | 20 | 35 | 1 |
| Bedrock | 22 | - | 1,000 kPa |

Static Loading Analysis

The results for the slope stability analyses under static conditions at Sections A-A, B-B, and C-C are shown on Figures 2A, 3A, and 4A, attached to the present memorandum. The factors of safety were found to be 1.2 and 0.9 at Section A-A and B-B under static conditions, respectively. Therefore, stable slope setback allowances from the top of slope have been provided to obtain a factor of safety greater than or equal to 1.5.



At Section C-C, the factor of safety was calculated to be 1.78, therefore a stable slope allowance is not required in this area.

Seismic Loading Analysis

An analysis considering seismic loading was also completed. A horizontal acceleration of 0.16 g was considered for all slopes. A factor of safety of 1.1 is considered to be satisfactory for stability analyses including seismic loading. The results of the slope stability analyses under seismic conditions are shown on Figures 2B, 3B, and 4B attached to the present memorandum.

The results indicate a factor of safety are greater than 1.1 under seismic conditions at Sections A-A and C-C. Therefore, the slope is considered stable under seismic conditions at this location.

However, the results indicate a factor of safety less than 1.1 beyond the top of slope for Section B-B. Based on these results, a stable slope setback of 7 m from the top of slope is required to achieve a factor of safety of at least 1.1 in the area of Section B-B. It should be noted that the stable slope setback associated with the seismic loading analysis governs the required stable slope setback over the static analysis for Section B-B.

Geotechnical Setback – Limit of Hazard Lands

Typically, the Limit of Hazard Lands setback is comprised of a stable slope allowance, toe erosion, and 6 m erosion access allowance. The Limit of Hazard Lands designation line for the subject site is indicated on Drawing PG6241-1 – Limit of Hazard Lands Plan, attached to the end of this memorandum.

Based on the analysis results, stable slope setbacks of 3 and 7 m at the locations of Sections A-A and B-B, respectively, are required for the slope to be stable under static and seismic conditions.

The toe erosion allowance is based on the nature of the soils, the observed current erosion activities, and the width and location of the current watercourse. Based on the soil profile encountered at the test hole locations, and our site observations as part of the slope stability assessment, a 1 m toe erosion allowance is considered suitable for the subject site.

Further, based on the generally accepted guidelines, a 6 m erosion access allowance is recommended for the subject site.



The results of the slope stability assessment indicate that Limit of Hazard Lands setbacks of 10, 14, and 7 m as measured from the top of the slope, should be provided for any proposed structures at the subject site in the areas of Section A-A, B-B, and C-C respectively, in order to provide a suitable factor of safety of 1.5 under static conditions and 1.1 under seismic conditions.

It should be noted that other setbacks may be applicable from the top of slope, such as those from the municipality or other regulatory agencies, and which may exceed the above-noted Limit of Hazard Lands setbacks.

4.0 General Recommendations

The existing vegetation on the slope face should not be removed as it contributes to the stability of the slope and reduces erosion. If the existing vegetation needs to be removed, it is recommended that a 100 to 150 mm of topsoil mixed with a hardy seed be placed across the exposed slope face. The use of an erosion control blanket may be necessary to minimize rill-type erosion until the vegetation takes root.

It is also recommended that the future roof drains which may be intended to discharge onto the slope be directed elsewhere, such as into 19 mm crushed stone drainage pits located on the property, and away from the top of slope.

We trust that the current submission meets your immediate requirements.

Best Regards,

Paterson Group Inc.

Fernanda Carozzi, PhD. Geoph.



Scott S. Dennis, P.Eng.

Attachments

- Photographs from Site Visit on April 20, 2022
- Figure 1 – Key Plan
- Drawing PG6241-1 – Limit of Hazard Lands Plan
- Soil Profile and Test Data sheets
- Figures 2 through 4 – Slope Stability Cross-Sections

Report Distribution

- Southwell Homes Ltd. (e-mail Copy)
- Paterson Group Inc. (1 copy)



Photographs from Site Visit – April 20, 2021

Photo 1: Photograph of area taken from top of slope looking to the east. Slope observed to be heavily covered with vegetation.



Photo 2: Photograph taken from top of slope looking to the north. Area of slope observed to be generally covered with mature vegetation such as bush, trees and grass. No signs of active erosion observed.



Photographs from Site Visit – April 20, 2021

Photo 3: Photo of face of slope taken from top of slope. Face of slope observed to be generally covered with vegetation and no signs of active erosion.



Photo 4: Photo of face of slope taken from toe of slope. Vegetation observed to be established throughout the surface. Subject site throughout left portion of photograph.



Photographs from Site Visit – April 20, 2021

Photo 5: Photo of slope taken from top of slope. Slope observed to be covered with mature vegetation. No signs of active erosion observed




Photo 6: Photo of general area of slope taken from top of slope, looking north. No signs of erosion observed through the area.





FIGURE 1

KEY PLAN



**TOP OF SLOPE
(BASED ON THE PATERSON
GROUP SITE VISIT ON APRIL
20, 2022)**

**LIMIT OF HAZARD LANDS
(BASED ON SLOPE
STABILITY ASSESSMENT
BY PATERSON GROUP)**


**30 m BUFFER FROM
WETLAND BOUNDARY
(AS MARKED BY BOWFIN
ENVIRONMENTAL
CONSULTING)**

**WETLAND BOUNDARY
(AS MARKED BY BOWFIN
ENVIRONMENTAL
CONSULTING)**

**LIMIT OF HAZARD LANDS
(AS MARKED BY MVCA)**

**30 m BUFFER FROM
WETLAND BOUNDARY
(AS MARKED BY BOWFIN
ENVIRONMENTAL
CONSULTING)**

- LEGEND:**
- BOREHOLE WITH MONITORING WELL LOCATION (2018)
 - DESTROYED MONITORING WELL LOCATION (2008)
 - TEST WELL LOCATION (2015)
 - MONITORING WELL LOCATION (BY OTHERS)
 - HAND AUGER LOCATION (2015)
 - TEST PIT LOCATION (2008)
 - 121.79 GROUND SURFACE ELEVATION (m)
 - [117.17] BEDROCK SURFACE ELEVATION (m)
 - {0.25} DEPTH TO BEDROCK (m)
 - (A)-(A') SLOPE STABILITY CROSS SECTION



9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

| NO. | REVISIONS | DATE | INITIAL |
|-----|-----------------------------|------------|---------|
| 1 | EXTENDING TOP OF SLOPE LINE | 10/11/2023 | SC |

SOUTHWELL HOMES LTD.

**GEOTECHNICAL INVESTIGATION
PROPOSED RESIDENTIAL SUBDIVISION
122 OLD MILL LANE**

APPLETON, ONTARIO

Title: LIMIT OF HAZARD LANDS PLAN

| | | | |
|--------------|--------|---------------|-----------------|
| Scale: | 1:2000 | Date: | 05/2022 |
| Drawn by: | YA | Report No.: | PG6241-1 |
| Checked by: | FC | Dwg. No.: | PG6241-1 |
| Approved by: | SD | Revision No.: | 1 |

p:\autocad\drawings\geotechnical\pg6241\pg6241-1-limit of hazard lands plan (rev.01).dwg

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP 2**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|----------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | |
| GROUND SURFACE | | | | | | 0 | 127.28 | | | | | |
| TOPSOIL | 0.10 | | | | | | | | | | | |
| FILL: Brown silty sand with cinder blocks | 0.53 | G | 1 | | | | | | | | | |
| Brown SILTY SAND | 0.81 | G | 2 | | | | | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 0.81m depth | | | | | | | | | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |
| | | | | | | | | RKI Eagle Rdg. (ppm) | | | | |
| | | | | | | | | ▲ Full Gas Resp. △ Methane Elim. | | | | |

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY Backhoe

DATE August 26, 2008

FILE NO. **PE1114**

HOLE NO. **TP 3**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|----------------------------------|---------------------------|-----|-----|------------------------------|---|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | | |
| GROUND SURFACE | | | | | | 0 | 127.94 | 20 | 40 | 60 | 80 | | |
| FILL: Dark brown silty clay with gravel and brick pieces 1.62 ----- Grey-brown SILTY CLAY with sand 2.34 ----- End of Test Pit TP terminated on bedrock surface @ 2.34m depth (GWL @ 1.6m depth) | | G | 1 | | | 1 | 126.94 | | | | | | ∇ |
| | | G | 2 | | | 2 | 125.94 | | | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 | |
| | | | | | | | | RKI Eagle Rdg. (ppm) | | | | | |
| | | | | | | | | ▲ Full Gas Resp. △ Methane Elim. | | | | | |

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.




FILE NO. **PE1114**

REMARKS

HOLE NO. **TP 4**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|--|--------|--------|----------|----------------|-----------|-----------|---|---------------------------|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.92 | 20 | 40 | 60 | 80 | |
| FILL: Brown sand and gravel with rubble 0.97 |  | G | 1 | | | | |  | | | | |
| | | | | | | | | | | | | |
| GLACIAL TILL: Brown silty sand with clay, gravel and cobbles 2.67 |  | G | 2 | | | | |  | | | | |
| | | | | | | | | | | | | |
| End of Test Pit TP terminated on bedrock surface @ 2.67m depth | | | | | | | |  | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
 ▲ Full Gas Resp. △ Methane Elim.

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP 5**

BORINGS BY Backhoe

DATE August 26, 2005

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|-------------------------------------|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.72 | 20 | 40 | 60 | 80 | |
| FILL: Brown silty sand with gravel and clay | [Cross-hatched pattern] | G | 1 | | | | | | | | | |
| | | | | | | 1 | 127.72 | | | | | |
| GLACIAL TILL: Brown silty clay with sand and gravel | [Upward-pointing triangles pattern] | G | 2 | | | | | | | | | |
| | | | | | | 1.30 | | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 1.83m depth | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP 6**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|---|--------|--------|----------|----------------|-----------|-----------|----------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 127.70 | 20 | 40 | 60 | 80 | |
| FILL: Dark brown silty sand with topsoil |  | G | 1 | | | | | | | | | |
| 0.53 | | | | | | | | | | | | |
| Brown SILTY SAND, some clay |  | G | 2 | | | | | | | | | |
| 0.99 | | | | | | | | | | | | |
| GLACIAL TILL: Grey-brown silty clay with sand, gravel and cobbles |  | G | 3 | | | 1 | 126.70 | | | | | |
| 1.20 | | | | | | | | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 1.20m depth | | | | | | | | | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |
| | | | | | | | | RKI Eagle Rdg. (ppm) | | | | |
| | | | | | | | | ▲ Full Gas Resp. △ Methane Elim. | | | | |

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletext Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY Backhoe

DATE August 26, 2008

FILE NO. **PE1114**

HOLE NO. **TP 7**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|----------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.63 | 20 | 40 | 60 | 80 | |
| FILL: Brown silty sand with gravel | | G | 1 | | | | | | | | | |
| 0.48 | | | | | | | | | | | | |
| FILL: Dark brown silty sand with clay and concrete pieces | | G | 2 | | | | | | | | | |
| 0.84 | | | | | | | | | | | | |
| FILL: Brown silty sand with gravel | | G | 3 | | | 1 | 127.63 | | | | | |
| 1.22 | | | | | | | | | | | | |
| GLACIAL TILL: Light brown silty sand with clay, gravel and cobbles | | G | 4 | | | | | | | | | |
| 2.34 | | | | | | 2 | 126.63 | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 2.34m depth | | | | | | | | | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |
| | | | | | | | | RKI Eagle Rdg. (ppm) | | | | |
| | | | | | | | | ▲ Full Gas Resp. △ Methane Elim. | | | | |

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP 8**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|--|--------|--------|------------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.92 | 20 | 40 | 60 | 80 | |
| FILL: Brown silty sand with clay, cobbles, steel and topsoil |  | G | 1 | | | 1 | 127.92 | | | | | |
| | | G | 2 | | | | | | | | | |
| End of Test Pit | 1.78 | | | | | | | | | | | |
| TP terminated on bedrock surface @ 1.78m depth | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP 9**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|--|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.84 | 20 | 40 | 60 | 80 | |
| FILL: Sand and gravel with concrete and steel pieces End of Test Pit TP terminated on bedrock surface @ 1.47m depth |  | G | 1 | | | 1 | 127.84 | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |

RKI Eagle Rdg. (ppm)
 ▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY Backhoe

DATE August 26, 2008

FILE NO. PE1114

HOLE NO. TP10

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction | |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|-------------------------------|---------------------------|--|--|------------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | | |
| GROUND SURFACE | | | | | | 0 | 127.73 | | | | | | |
| TOPSOIL | | G | 1 | | | | | | | | | | |
| Brown SILTY SAND , trace clay | 0.23 | G | 2 | | | | | | | | | | |
| GLACIAL TILL: Grey-brown silty clay with sand, gravel and cobbles | 0.48 | G | 3 | | | | | | | | | | |
| End of Test Pit | 0.99 | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 0.99m depth | | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
 ▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP12**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|-------------|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | |
| GROUND SURFACE | | | | | | 0 | 128.16 | | | | | |
| FILL: Brown sand with gravel | 0.15 | | | | | | | | | | | |
| TOPSOIL | | | | | | | | | | | | |
| Brown SILTY CLAY with sand | 0.33 | G | 2 | | | | | | | | | |
| | 0.53 | G | 1 | | | | | | | | | |
| | | G | 3 | | | | | | | | | |
| GLACIAL TILL: Light brown silty sand with clay, gravel and cobbles | | G | 4 | | | 1 | 127.16 | | | | | |
| | 1.37 | | | | | | | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 1.37m depth | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.


FILE NO. **PE1114**

REMARKS

HOLE NO. **TP13**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|---|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.85 | 20 | 40 | 60 | 80 | |
| FILL: Sand and gravel with topsoil |  | G | 1 | | | | | | | | | |
| | 1.12 | | | | | 1 | 127.85 | | | | | |
| Brown SILTY SAND, some clay |  | G | 2 | | | | | | | | | |
| | 1.73 | | | | | 2 | 126.85 | | | | | |
| GLACIAL TILL: Light brown silty sand with clay, gravel and cobbles |  | G | 3 | | | | | | | | | |
| | 3.05 | | | | | 3 | 125.85 | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 3.05m depth | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY Backhoe

DATE August 26, 2008

FILE NO. PE1114

HOLE NO. TP14

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|-------------|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.82 | 20 | 40 | 60 | 80 | |
| FILL: Brown silty sand with clay, concrete and steel 1.30 GLACIAL TILL: Light brown silty sand with clay, gravel and cobbles 1.42 End of Test Pit TP terminated on bedrock surface @ 1.42m depth | | G | 1 | | | 1 | 127.82 | | | | | |
| | | G | 2 | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
 ▲ Full Gas Resp. △ Methane Elim.

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY Backhoe

DATE August 26, 2008

FILE NO. **PE1114**

HOLE NO. **TP15**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|---|--------|--------|------------|----------------|-----------|-----------|-------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 128.04 | 20 | 40 | 60 | 80 | |
| <p>FILL: Mixture of topsoil, sand, silty clay, gravel and wood</p> <p>0.51</p> <p>End of Test Pit</p> <p>TP terminated on bedrock surface @ 0.51m depth</p> |  | G | 1 | | | | ▲ | | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |

RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP16**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|--|---|--------|--------|------------|----------------|-----------|-----------|-------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 127.95 | 20 | 40 | 60 | 80 | |
| FILL: Sand and gravel with clay, wood and slag End of Test Pit TP terminated on bedrock surface @ 0.91m depth |  | G | 1 | | | | | △ | | | | |
| | | G | 2 | | | | | | △ | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |

RKI Eagle Rdg. (ppm)
 ▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP18**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|-------------|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|-----|-----|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | 0 | 125.97 | 20 | 40 | 60 | 80 | |
| <p>FILL: Silty sand with clay, topsoil, wood and slag</p> <p>End of Test Pit</p> <p>TP terminated on bedrock surface @ 0.63m depth</p> | 0.63 | G | 1 | | | | | ▲ | | | | |
| | | | | | | | | 100 | 200 | 300 | 400 | 500 |

RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY Backhoe

DATE August 26, 2008

FILE NO. PE1114

HOLE NO. TP19

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|----|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | 20 | 40 | | 60 |
| GROUND SURFACE | | | | | | 0 | | | | | | | |
| TOPSOIL End of Test Pit | 0.03 | | | | | | | | | | | | |
| TP terminated on bedrock surface @ 0.03m depth | | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **TP21**

BORINGS BY Backhoe

DATE August 26, 2008

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction |
|---|-------------|--------|--------|----------|----------------|-----------|-----------|-------------------------------|---------------------------|--|--|------------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ● Volatile Organic Rgd. (ppm) | ○ Lower Explosive Limit % | | | |
| GROUND SURFACE | | | | | | | | | | | | |
| FILL: Brown silty sand with clay and gravel | 0.20 | G | 1 | | | 0 | 128.19 | △ | | | | |
| TOPSOIL | 0.63 | G | 2 | | | | | △ | | | | |
| GLACIAL TILL: Brown silty clay with sand, gravel and cobbles | 1.12 | G | 3 | | | 1 | 127.19 | △ | | | | |
| End of Test Pit TP terminated on bedrock surface @ 1.12m depth | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rgd. (ppm)
▲ Full Gas Resp. △ Methane Elim.

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

REMARKS

BORINGS BY CME 55 Power Auger

DATE 26 Aug 08

FILE NO. **PE1114**

HOLE NO. **MW 1-08**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Monitoring Well Construction |
|---|---|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|------------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Lower Explosive Limit % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Silty sand with gravel |  | AU | 1 | | | 0 | 127.46 | | | | | |
| | 0.86 | RC | 1 | 91 | 0 | 1 | 126.46 | | | | | |
| | | RC | 2 | 90 | 60 | 2 | 125.46 | | | | | |
| | | RC | 3 | 88 | 82 | 3 | 124.46 | | | | | |
| | | RC | 4 | 100 | 44 | 4 | 123.46 | | | | | |
| | | RC | 5 | 90 | 73 | 5 | 122.46 | | | | | |
| BEDROCK: Limestone | | RC | 6 | 95 | 92 | 6 | 121.46 | | | | | |
| | | RC | 7 | 100 | 78 | 7 | 120.46 | | | | | |
| | | RC | 8 | 97 | 80 | 8 | 119.46 | | | | | |
| | | RC | 9 | 100 | 100 | 9 | 118.46 | | | | | |
| | | RC | 10 | | | 10 | 117.46 | | | | | |
| | | RC | 11 | | | 11 | 116.46 | | | | | |
| | | RC | 12 | | | 12 | 115.46 | | | | | |
| End of Monitoring Well (GWL @ 9.86m-Sept. 2/08) | 12.19 | | | | | | | | | | | |

100 200 300 400 500
Gastech 1314 Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Phase II-Environmental Site Assessment
Former Appletex Mill
Appleton, Ontario

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.

FILE NO. **PE1114**

REMARKS

HOLE NO. **MW 2-08**

BORINGS BY CME 55 Power Auger

DATE 26 Aug 08

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Monitoring Well Construction | |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|------------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Lower Explosive Limit % | | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | | |
| FILL: Silty sand with gravel and concrete pieces | | | | | | 0 | 128.08 | | | | | | |
| | | | | | | 1 | 127.08 | | | | | | |
| | | | | | | 2 | 126.08 | | | | | | |
| | | RC | 1 | 85 | 73 | 3 | 125.08 | | | | | | |
| | | RC | 2 | 93 | 60 | 4 | 124.08 | | | | | | |
| | | RC | 3 | 100 | 100 | 5 | 123.08 | | | | | | |
| | | RC | 4 | 97 | 87 | 6 | 122.08 | | | | | | |
| | | RC | 5 | 92 | 82 | 7 | 121.08 | | | | | | |
| | | RC | 6 | 100 | 93 | 8 | 120.08 | | | | | | |
| | | RC | 7 | 93 | 88 | 9 | 119.08 | | | | | | |
| | | RC | 8 | 100 | 100 | 10 | 118.08 | | | | | | |
| | | RC | | | | 11 | 117.08 | | | | | | |
| | | RC | | | | 12 | 116.08 | | | | | | |
| BEDROCK: Limestone | | | | | | | | | | | | | |
| End of Monitoring Well (GWL @ 7.30m-Sept. 2/08) | | | | | | | | | | | | | |

100 200 300 400 500
Gastech 1314 Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

DATUM Ground surface elevations provided by G. A. Smith Surveying Ltd.


FILE NO. **PE1114**

REMARKS

HOLE NO. **MW 3-08**

BORINGS BY CME 55 Power Auger

DATE 26 Aug 08



100 200 300 400 500
Gastech 1314 Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

REMARKS

FILE NO.
PH2723

HOLE NO.
TH 1

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|--|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Dark brown silty sand with gravel |  | G | 1 | | | 0 | 126.0 | | | | | |
| | | | | | | 1 | 125.0 | | | | | |
| End of Test Hole | 1.55 | | | | | | | | | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | 100 |
| | | | | | | | | Shear Strength (kPa) | | | | |
| | | | | | | | | ▲ Undisturbed △ Remoulded | | | | |

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith
Surveying Limited and, as such, are approximate only.


REMARKS

FILE NO.
PH2723

HOLE NO.
TH 2

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|--|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | 0 | 128.3 | 20 | 40 | 60 | 80 | |
| FILL: Dark brown silty sand with gravel End of Test Hole |  | G | 1 | | | 1 | 127.3 |  | | | | |
| | | | | | | | | Shear Strength (kPa) ▲ Undisturbed △ Remoulded | | | | |

1.55

End of Test Hole

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

REMARKS

FILE NO.
PH2723

HOLE NO.
TH 3

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|--|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Dark brown silty sand with gravel |  | G | 1 | | | 0 | 126.0 | | | | | |
| | | | | | | 1 | 125.0 | | | | | |
| End of Test Hole | 1.55 | | | | | | | | | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | 100 |
| | | | | | | | | Shear Strength (kPa) | | | | |
| | | | | | | | | ▲ Undisturbed △ Remoulded | | | | |

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

REMARKS

FILE NO.
PH2723

HOLE NO.
TH 4

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|--|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | 0 | 127.9 | 20 | 40 | 60 | 80 | |
| TOPSOIL | 0.05 | | | | | | | | | | | |
| FILL: Dark brown silty sand with some gravel and cobbles to sand-gravel, trace silt and clay |  | G | 1 | | | | | | | | | |
| | | | | | | 1 | 126.9 | | | | | |
| End of Test Pit | 1.13 | | | | | | | | | | | |
| Practical refusal to augering on inferred bedrock surface at 1.13m depth | | | | | | | | | | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | 100 |
| | | | | | | | | Shear Strength (kPa) | | | | |
| | | | | | | | | ▲ Undisturbed △ Remoulded | | | | |

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

FILE NO.
PH2723

REMARKS

HOLE NO.
TH 5

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|----------------------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Light brown silty sand | [Cross-hatched pattern] | G | 1 | | | 0 | 127.9 | | | | | |
| | | | | | | 0.59 | | | | | | |
| Very stiff, brown SILTY CLAY , trace gravel | [Diagonal hatched pattern] | G | 2 | | | 1 | 126.9 | | | | | |
| | | | | | | 1.05 | | | | | | |
| End of Test Hole | | | | | | | | | | | | |
| Practical refusal to augering on inferred bedrock surface at 1.05m depth | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

REMARKS


FILE NO.
PH2723

HOLE NO.
TH 6

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | | |
| TOPSOIL | 0.06 | | | | 0 | 128.6 | | | | | | | |
| FILL: Brown silty sand with clay | 0.35 | | | | | | | | | | | | |
| End of Test Hole Practical refusal to augering on inferred bedrock surface at 0.35m depth | | | | | | | | | | | | | |



SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

REMARKS

BORINGS BY Hand Auger

DATE August 28, 2015

FILE NO.
PH2723

HOLE NO.
TH 7

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | | |
| TOPSOIL | 0.04 | | | | 0 | 123.9 | | | | | | | |
| FILL: Brown silty sand with clay | | | | | | | | | | | | | |
| End of Test Hole | 0.65 | | | | | | | | | | | | |
| Practical refusal to augering on inferred bedrock surface at 0.65m depth | | | | | | | | | | | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | 100 | |
| | | | | | | | | Shear Strength (kPa) | | | | | |
| | | | | | | | | ▲ Undisturbed △ Remoulded | | | | | |

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

REMARKS

FILE NO.
PH2723

HOLE NO.
TH 8

BORINGS BY Hand Auger

DATE August 28, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 124.7 | | | | | | |
| TOPSOIL | 0.04 | | | | | | | | | | | | |
| FILL: Brown silty sand with clay | | | | | | | | | | | | | |
| End of Test Hole | 0.91 | | | | | | | | | | | | |
| Practical refusal to augering on inferred bedrock surface at 0.91m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith Surveying Limited and, as such, are approximate only.

FILE NO.
PH2723

REMARKS

HOLE NO.
TH 9

BORINGS BY Hand Auger

DATE September 9, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | | |
| TOPSOIL | 0.03 | | | | 0 | 124.5 | | | | | | | |
| SILTY SAND with clay | 0.34 | G | 1 | | | | | | | | | | |
| End of Test Hole | | | | | | | | | | | | | |
| Practical refusal to augering on inferred bedrock surface at 0.34m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Ground surface elevations interpolated from topo plan prepared by G.A. Smith
Surveying Limited and, as such, are approximate only.

REMARKS

FILE NO.
PH2723

HOLE NO.
TH11

BORINGS BY Hand Auger

DATE September 9, 2015

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | | |
| TOPSOIL | 0.02 | | | | 0 | 124.6 | | | | | | | |
| SILTY SAND, some clay | 0.18 | | | | | | | | | | | | |
| End of Test Hole | | | | | | | | | | | | | |
| Practical refusal to augering on inferred bedrock surface at 0.18m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP1**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Brown sand, silt, clay, rock and burnt wood debris. Slightly moist. 0.70 | X | G | 1 | | | 0 | 126.25 | | | | | |
| FILL: Brown sand, silt and broken stone. Dry. 1.10 | X | G | 2 | | | 1 | 125.25 | | | | | |
| FILL: Gravel, old wires, black plastic pieces. Drainage tile (pea stone) at 1.3m depth. 1.30 | X | | | | | | | | | | | |
| FILL: Brown sand, silt and fabric debris 1.60 | X | G | 3 | | | | | | | | | |
| End of Test Pit Refusal on bedrock at 1.60 m depth | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. PH2723

HOLE NO. TP2

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Brown silt, sand and clay with gravel. Slightly moist. | 0.20 | G | 4 | | | 0 | 128.17 | | | | | |
| FILL: Light brown silt, sand, some gravel. Slightly moist. | 0.40 | G | 5 | | | | | | | | | |
| FILL: Black sand and silt, trace clay and charcoal. Slightly moist. | 0.70 | G | 6 | | | | | | | | | |
| | | G | 8 | | | | | | | | | |
| FILL: Light brown coarse sand, silt, gravel. Moist. | | G | 7 | | | 1 | 127.17 | | | | | |
| | 1.70 | | | | | | | | | | | |
| End of Test Pit | | | | | | | | | | | | |
| Refusal on bedrock at 1.70 m depth | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP3**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 128.60 | | | | | | |
| FILL: Dark brown sand, silt, clay topsoil. Moist | 0.10 | | | | | | | | | | | | |
| FILL: Light brown sand, silt, clay and gravel. Slightly moist. | | G | 8 | | | 1 | 127.60 | | | | | | |
| End of Test Pit | 1.83 | | | | | | | | | | | | |
| Refusal on bedrock at 1.83 m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP4**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| <p>FILL: Brown sandy silt, trace clay topsoil. Slightly moist.</p> <p>0.09</p> | X | | | | 0 | 127.95 | | | | | | |
| <p>FILL: Light brown sand, silt, clay, gravel with debris (wood and plastic). Slightly moist.</p> <p>1.92</p> | X | G | 9 | | 1 | 126.95 | | | | | | |
| <p>End of Test Pit</p> <p>Refusal on bedrock at 1.92 m depth</p> | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP5**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|---|-------------|--------|--------|----------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 128.78 | | | | | | |
| FILL: Brown sandy silt with roots topsoil. Moist. | 0.11 | | | | | | | | | | | | |
| FILL: Light brown fine sand, silt, some clay and gravel. Slight moist. | | G | 10 | | | | | | | | | | |
| | 1.17 | | | | | 1 | 127.78 | | | | | | |
| End of Test Pit Refusal on bedrock at 1.17 m depth | | | | | | | | | | | | | |

○ Water Content %

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP7**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 128.42 | | | | | | |
| FILL: Brown sandy silt topsoil. Dry. | | | | | | | | | | | | | |
| 0.38 | | | | | | | | | | | | | |
| FILL: Light brown sandy silt, trace clay, debris. Dry. | | G | 12 | | | | | | | | | | |
| 1.17 | | | | | | 1 | 127.42 | | | | | | |
| End of Test Pit | | | | | | | | | | | | | |
| Refusal on bedrock at 1.17 m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP8**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | | | | | | | |
| FILL: Brown to light brown sandy silt. Dry. | | G | 13 | | | 1 | | | | | | | |
| | | | | | | 1.76 | | | | | | | |
| End of Test Pit | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP12**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 127.85 | | | | | | |
| FILL: Dark brown sandy silt topsoil. Slightly moist. | X | | | | | | | | | | | | |
| 0.49 | | | | | | | | | | | | | |
| FILL: Light brown fine sand, silt, trace clay. Dry. | X | G | 17 | | | | | | | | | | |
| 0.88 | | | | | | | | | | | | | |
| End of Test Pit Refusal on bedrock at 0.88 m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP13**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|--|--------|--------|------------|----------------|-----------|------------------------------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Brown mixture of sand, silt, clay and gravel. Dry. |  | G | 18 | | 0 | 128.03 | | | | | | |
| | | | | | 1 | 127.03 | | | | | | |
| End of Test Pit Refusal on bedrock at 1.27 m depth | 1.27 | | | | | | | | | | | |
| | | | | | | | | 20 | 40 | 60 | 80 | 100 |
| | | | | | | | Shear Strength (kPa) | | | | | |
| | | | | | | | ▲ Undisturbed △ Remoulded | | | | | |

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP14**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 126.89 | | | | | | |
| FILL: Brown sandy silt, gravel. Slightly moist. | 0.28 | G | 19 | | | | | | | | | | |
| End of Test Pit | | | | | | | | | | | | | |
| Refusal on bedrock at 0.28 m depth | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP15**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|---|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Brown sandy silt, clay, boulders, concrete, asphalt, plastic and steel debris. Slightly moist. |  | G | 20 | | | 0 | 121.62 | | | | | |
| | | | | | | 1 | 120.62 | | | | | |
| FILL: Grey/black clay, sand, gravel and organics. Very moist. |  | G | 21 | | | 2 | 119.62 | | | | | |
| | | | | | | 3 | 118.62 | | | | | |
| End of Test Pit Test pit terminated due to maximum reach of backhoe. | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP16**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 121.06 | | | | | | |
| FILL: Brown sandy silt, clay and cobbles/boulders. Moist. | X | G | 24 | | | 1 | 120.06 | | | | | | |
| | | | | | | 2 | 119.06 | | | | | | |
| FILL: Grey clay, sand | X | G | 22 | | | 2 | 119.06 | | | | | | |
| Black organics, cat tails. Very wet. | H | G | 23 | | | 3 | 118.06 | | | | | | |
| | | | | | | 4 | | | | | | | |
| End of Test Pit Test pit terminated due to maximum reach of backhoe. (GWL @ 1.57 m depth) | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP17**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction | |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | | |
| GROUND SURFACE | | | | | | 0 | 120.63 | | | | | | |
| FILL: Brown sandy silt topsoil. Slightly moist. | 0.13 | | | | | | | | | | | | |
| FILL: Brown to dark brown sandy silt, clay, gravel, brick, plastic and concrete debris. Moist. | | G | 27 | | | 1 | 119.63 | | | | | | |
| | 1.92 | | | | | | | | | | | | |
| FILL: Grey clay, sand. Very wet. | | G | 26 | | | 2 | 118.63 | | | | | | |
| | 2.34 | | | | | | | | | | | | |
| End of Test Pit Test pit terminated due to inflow of groundwater. (GWL @ 1.78 m depth) | | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP18**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|--|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Brown silty sand, some clay, gravel. Dry |  | G | 29 | | | 0 | 121.74 | | | | | |
| | | | | | | 1 | 120.74 | | | | | |
| FILL: Black to grey clay, sand, fabric, garbage bag. Slightly wet. |  | G | 28 | | | 2 | 119.74 | | | | | |
| | | | | | | 3 | 118.74 | | | | | |
| End of Test Pit Test pit terminated due to maximum reach of backhoe. | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP19**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Brown sandy silt topsoil. Slightly moist. | 0.13 | | | | | 0 | 120.63 | | | | | |
| FILL: Brown to dark brown sandy silt, clay, gravel, brick, plastic and concrete debris. Moist. | | | | | | 1 | 119.63 | | | | | |
| FILL: Grey clay, sand. Very wet. | 1.92 | | | | | 2 | 118.63 | | | | | |
| End of Test Pit Test pit terminated due to inflow of groundwater. (GWL @ 1.78 m depth) | 2.34 | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

SOIL PROFILE AND TEST DATA

Proposed Residential Subdivision
Old Mill Lane
Appleton, Ontario

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP21**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|--|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | 20 | 40 | 60 | 80 | |
| GROUND SURFACE | | | | | | 0 | | | | | | |
| FILL: Brown sand, silt, clay, stone, wood and fabric debris | | G | 31 | | | 1 | | | | | | |
| | | | | | | 1.88 | | | | | | |
| End of Test Pit | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP22**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|---|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Dark brown sand, silt, gravel, wood, fabric, concrete, glass, metal and plastic debris. Dry. |  | G | 33 | | | 0 | 123.68 | | | | | |
| | | | | | | 1 | 122.68 | | | | | |
| FILL: Brown sand, silt, metal, glass, wood and plastic debris. gravel. Dry. |  | G | 34 | | | | | | | | | |
| End of Test Pit Refusal on bedrock at 1.82 m depth | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
 ▲ Undisturbed △ Remoulded

DATUM Geodetic

REMARKS

BORINGS BY Backhoe

DATE August 18, 2016

FILE NO. **PH2723**

HOLE NO. **TP24**

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Pen. Resist. Blows/0.3m ● 50 mm Dia. Cone | | | | Piezometer Construction |
|---|-------------|--------|--------|------------|----------------|-----------|-----------|--|----|----|----|-------------------------|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ○ Water Content % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | |
| FILL: Dark brown sandy silt, some clay. Slightly moist. | 0.25 | G | 39 | | | 0 | 123.16 | | | | | |
| FILL: Light brown sandy silt, some clay and gravel. Dry. | 1.67 | G | 38 | | | 1 | 122.16 | | | | | |
| FILL: Dark grey clay with sand and boulders. Wet. | 2.23 | G | 37 | | | 2 | 121.16 | | | | | |
| End of Test Pit Refusal on large boulders at 2.23 m depth. | | | | | | | | | | | | |

20 40 60 80 100
Shear Strength (kPa)
▲ Undisturbed △ Remoulded

DATUM

REMARKS

BORINGS BY CME 55 Power Auger


DATE March 16, 2018

FILE NO.

PE1114

HOLE NO.

BH 1-18



DATUM

REMARKS

BORINGS BY CME 55 Power Auger

DATE March 16, 2018

FILE NO.

PE1114

HOLE NO.

BH 2-18

| SOIL DESCRIPTION | STRATA PLOT | SAMPLE | | | | DEPTH (m) | ELEV. (m) | Photo Ionization Detector | | | | Monitoring Well Construction | |
|---|--|--------|--------|------------|----------------|-----------|-----------|-------------------------------|---------------------------|----|----|------------------------------|--|
| | | TYPE | NUMBER | RECOVERY % | N VALUE or RQD | | | ● Volatile Organic Rdg. (ppm) | ○ Lower Explosive Limit % | | | | |
| GROUND SURFACE | | | | | | | | 20 | 40 | 60 | 80 | | |
| FILL: Topsoil with organics, trace gravel, cobbles and boulders |  | RC | 1 | 100 | 52 | 0 | | | | | | | |
| | | RC | 2 | 100 | 94 | 1 | | | | | | | |
| BEDROCK: Grey limestone |  | RC | 3 | 100 | 68 | 2 | | | | | | | |
| | | RC | 4 | 100 | 93 | 3 | | | | | | | |
| | | RC | 5 | 100 | 92 | 4 | | | | | | | |
| End of Borehole (GWL @ 3.35m - June 7, 2018) | | | | | | | | | | | | | |

100 200 300 400 500
RKI Eagle Rdg. (ppm)
▲ Full Gas Resp. △ Methane Elim.

SYMBOLS AND TERMS

SOIL DESCRIPTION

Behavioural properties, such as structure and strength, take precedence over particle gradation in describing soils. Terminology describing soil structure are as follows:

| | | |
|------------------|---|--|
| Desiccated | - | having visible signs of weathering by oxidation of clay minerals, shrinkage cracks, etc. |
| Fissured | - | having cracks, and hence a blocky structure. |
| Varved | - | composed of regular alternating layers of silt and clay. |
| Stratified | - | composed of alternating layers of different soil types, e.g. silt and sand or silt and clay. |
| Well-Graded | - | Having wide range in grain sizes and substantial amounts of all intermediate particle sizes (see Grain Size Distribution). |
| Uniformly-Graded | - | Predominantly of one grain size (see Grain Size Distribution). |

The standard terminology to describe the strength of cohesionless soils is the relative density, usually inferred from the results of the Standard Penetration Test (SPT) 'N' value. The SPT N value is the number of blows of a 63.5 kg hammer, falling 760 mm, required to drive a 51 mm O.D. split spoon sampler 300 mm into the soil after an initial penetration of 150 mm.

| Relative Density | 'N' Value | Relative Density % |
|------------------|-----------|--------------------|
| Very Loose | <4 | <15 |
| Loose | 4-10 | 15-35 |
| Compact | 10-30 | 35-65 |
| Dense | 30-50 | 65-85 |
| Very Dense | >50 | >85 |

The standard terminology to describe the strength of cohesive soils is the consistency, which is based on the undisturbed undrained shear strength as measured by the in situ or laboratory vane tests, penetrometer tests, unconfined compression tests, or occasionally by Standard Penetration Tests.

| Consistency | Undrained Shear Strength (kPa) | 'N' Value |
|-------------|--------------------------------|-----------|
| Very Soft | <12 | <2 |
| Soft | 12-25 | 2-4 |
| Firm | 25-50 | 4-8 |
| Stiff | 50-100 | 8-15 |
| Very Stiff | 100-200 | 15-30 |
| Hard | >200 | >30 |

SYMBOLS AND TERMS (continued)

SOIL DESCRIPTION (continued)

Cohesive soils can also be classified according to their "sensitivity". The sensitivity is the ratio between the undisturbed undrained shear strength and the remoulded undrained shear strength of the soil.

Terminology used for describing soil strata based upon texture, or the proportion of individual particle sizes present is provided on the Textural Soil Classification Chart at the end of this information package.

ROCK DESCRIPTION

The structural description of the bedrock mass is based on the Rock Quality Designation (RQD).

The RQD classification is based on a modified core recovery percentage in which all pieces of sound core over 100 mm long are counted as recovery. The smaller pieces are considered to be a result of closely-spaced discontinuities (resulting from shearing, jointing, faulting, or weathering) in the rock mass and are not counted. RQD is ideally determined from NXL size core. However, it can be used on smaller core sizes, such as BX, if the bulk of the fractures caused by drilling stresses (called "mechanical breaks") are easily distinguishable from the normal in situ fractures.

| RQD % | ROCK QUALITY |
|--------------|--|
| 90-100 | Excellent, intact, very sound |
| 75-90 | Good, massive, moderately jointed or sound |
| 50-75 | Fair, blocky and seamy, fractured |
| 25-50 | Poor, shattered and very seamy or blocky, severely fractured |
| 0-25 | Very poor, crushed, very severely fractured |

SAMPLE TYPES

| | | |
|----|---|---|
| SS | - | Split spoon sample (obtained in conjunction with the performing of the Standard Penetration Test (SPT)) |
| TW | - | Thin wall tube or Shelby tube |
| PS | - | Piston sample |
| AU | - | Auger sample or bulk sample |
| WS | - | Wash sample |
| RC | - | Rock core sample (Core bit size AXT, BXL, etc.). Rock core samples are obtained with the use of standard diamond drilling bits. |

SYMBOLS AND TERMS (continued)

GRAIN SIZE DISTRIBUTION

| | | |
|-----|---|--|
| MC% | - | Natural moisture content or water content of sample, % |
| LL | - | Liquid Limit, % (water content above which soil behaves as a liquid) |
| PL | - | Plastic limit, % (water content above which soil behaves plastically) |
| PI | - | Plasticity index, % (difference between LL and PL) |
| Dxx | - | Grain size which xx% of the soil, by weight, is of finer grain sizes These grain size descriptions are not used below 0.075 mm grain size |
| D10 | - | Grain size at which 10% of the soil is finer (effective grain size) |
| D60 | - | Grain size at which 60% of the soil is finer |
| Cc | - | Concavity coefficient = $(D_{30})^2 / (D_{10} \times D_{60})$ |
| Cu | - | Uniformity coefficient = D_{60} / D_{10} |

Cc and Cu are used to assess the grading of sands and gravels:

Well-graded gravels have: $1 < Cc < 3$ and $Cu > 4$

Well-graded sands have: $1 < Cc < 3$ and $Cu > 6$

Sands and gravels not meeting the above requirements are poorly-graded or uniformly-graded.

Cc and Cu are not applicable for the description of soils with more than 10% silt and clay (more than 10% finer than 0.075 mm or the #200 sieve)

CONSOLIDATION TEST

| | | |
|------------|---|--|
| p'_o | - | Present effective overburden pressure at sample depth |
| p'_c | - | Preconsolidation pressure of (maximum past pressure on) sample |
| Ccr | - | Recompression index (in effect at pressures below p'_c) |
| Cc | - | Compression index (in effect at pressures above p'_c) |
| OC Ratio | | Overconsolidation ratio = p'_c / p'_o |
| Void Ratio | | Initial sample void ratio = volume of voids / volume of solids |
| Wo | - | Initial water content (at start of consolidation test) |

PERMEABILITY TEST

| | | |
|---|---|--|
| k | - | Coefficient of permeability or hydraulic conductivity is a measure of the ability of water to flow through the sample. The value of k is measured at a specified unit weight for (remoulded) cohesionless soil samples, because its value will vary with the unit weight or density of the sample during the test. |
|---|---|--|

SYMBOLS AND TERMS (continued)


STRATA PLOT




Topsoil



Asphalt




Fill




Peat




Sand




Silty Sand




Silt



Sandy Silt




Clay




Silty Clay




Clayey Silty Sand



Glacial Till




Shale



Bedrock

MONITORING WELL AND PIEZOMETER CONSTRUCTION

MONITORING WELL CONSTRUCTION



PIEZOMETER CONSTRUCTION





Figure 2A - Section A - Existing Conditions -Static Loading






Figure 3A - Section B - Existing Conditions - Static Loading




Figure 3B - Section B - Existing Conditions - Seismic Loading




Figure 4A - Section C - Existing Conditions -Static Loading

